



Fig. 1 Formation of the porous structure in the initial phase of reducing the volume stress during tyre rubber crushing

BEST AVAILABLE COPY




Fig. 2 Microcrack formation due to pore tearing during a marked volume stress reduction on tyre rubber crushing

BEST AVAILABLE COPY




Fig. 3.